

SECRET**PRIORITY****OUT55225**

P 120008Z

FM NPIC WASHDC

TO RUCSC/SAC OFFUTT AFB OMAHA NEB

RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAA/2D RTS BARKSDALE AFB LA

RUEKDA/DIA WASHDC

RUECYN/NAVRECONTECHSUPPCEN SUITLAND ND

RUEPIA/CIA WASHDC

RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF

RUWGAA/2AF BARKSDALE AFB LA

BT

SECRET CITE NPIC 4030.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-122 WAS USED IN MISSION 3993 FLOWN ON 9 MARCH 1965;
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND RESOLUTION GOOD.

B. 9R SIDE: EDGE FOG IS PRESENT INTERMITTENTLY ALONG THE
OUTBOARD EDGE. MINUS DENSITY DOTS OCCUR 4.6 INCHES FROM THE INBOARD
EDGE 1.55 INCHES APART, FROM FRAME 1 TO 138. ON FRAME 139 THE MINUS
DENSITY DOTS BECOME 2.32 INCHES APART AND CONTINUE THROUGH THE FIRST
HALF OF THE MISSION. THE CAMERA NUMBER IN THE DATA CHAMBER IS
DIFFICULT TO READ. HEAT SPLICES ARE LOCATED ON FRAMES 1227, 1690,
AND 2522. A MANUFACTURING SPLICE IS PRESENT ON FRAME 747. FOG OF

1965 MAR 12 00 26Z
12 MAR 1965

COPIES RECEIVED 7			
CyNo.	Office	Act.	Rec'd
1	Master File		
2	OS		
	ADMIN		
	SEC BR		
	P&DS		
	CSD		
	IPD		
	PD		
	PSD		
3/4	TID	<input checked="" type="checkbox"/>	
	PAG		
	CIA/PID		
	DIAX #4		
	SPAD		
	NSA LO		
	DIAAP		
	Destroyed		

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

-2-

VARYING DEGREES IS PRESENT ON FRAME 2522 TO 2529.

C. 9L SIDE: MINUS DENSITY DOTS OCCUR 4.15 INCHES AND 0.7 INCHES FROM THE INBOARD EDGE THROUGHOUT THE FIRST PART OF THE MISSION. NUMEROUS PINHOLES ARE LOCATED ON FRAME 926. NUMEROUS PROCESSING STREAKS, PARALLEL TO THE MAJOR AXIS OF THE FILM, START ON FRAME 925 AND CONTINUE THROUGHOUT THE REMAINDER OF THE MISSION. PROCESSING STREAKS PARALLEL TO THE MINOR AXIS OF THE FILM, UP TO 0.5 INCHES WIDE, OCCUR INTERMITTENTLY FROM FRAME 925 TO THE END OF THE MISSION. A HEAT SPLICE IS PRESENT ON FRAME 1249 AND A MANUFACTURING SPLICE ON FRAME 579.

D. BOTH SIDES: EDGE STATIC OF VARYING DEGREES OCCURS ALONG BOTH EDGES OF BOTH SIDES THROUGHOUT THE MISSION. MODE I WAS USED DURING THIS MISSION FROM FRAME 1 TO 276. MODE V WAS USED FROM FRAME 277 TO THE END OF THE MISSION. THE VERTICAL INDICATOR LIGHTS FAILED INTERMITTENTLY ON BOTH SIDES DURING THE MISSION. THE LAST TITLED FRAME IS 2532.

E. THERE WERE NO MAJOR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 35 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/